

Faults Algorithms:

1. Machine Does Not Work:




2. Degree of Drying can not be reached or drying time is too long:



Cooling circuit system includes the compressor, copper tubes and the heat exchangers (condenser and evaporator)

3. Drum is not rotating:



4. Program does not progress although the tank is empty:

